

Suggested Routing:

☐ Service ☐ Sales ☐ Parts

Date: January 22, 2010

No. 2010-01(S)

MODELS: 2009 Evinrude E-TEC 75-90 HP
Outboards

SUBJECT: Incorrect Wiring Diagram in Service
Manual, P/N 5007811


Dear Evinrude/Johnson® Dealers:

This communication is to inform Evinrude/Johnson dealers of an incorrect wiring diagram in the 2009 Evinrude E-TEC 75-90 HP Service Manual, P/N 5007811.

Service manual, P/N 5007811, was included in the 2009 Evinrude E-TEC Service Manual Set, P/N 5007823. These service manual sets were automatically shipped to North American dealers through the essential literature program in June of 2009.

This “replacement” wiring diagram (included with this bulletin) should be attached to the original wiring diagram in the service manual. Dealers are asked to place the 2009 Evinrude E-TEC 75-90 HP wiring diagram, P/N 355362, in 2009 Evinrude E-TEC 75-90 HP Service Manual, P/N 5007811.

Additional wiring diagrams can be ordered through P&A. Order Diagram-75/90 2009, P/N 5008294, as needed.



P/N 355362 – New wiring diagram